

Log

Date	Hour (UTC)	Note
2015/11/6	3:15	Start inline → seeing a lot of Dematiella Debubble x2

→ 4:14 ← Restart Acq Inline
↳ Disable view image off 4 min
↳ Disable Debug
Dashboard updated every 20 min

2015/11/7	12:45	Stop Acq ↳ Activate Expert tab to change Flashlamp Delay Flashlamp already 599µs should be between 60-200
-----------	-------	---

12:50	Start Acq
-------	-----------


13:24	Stop Acq + Init ↳ Open IFCB to adjust camera Reset Flashlamp delay to 130 not possible ↳ Flashlamp delay is still 599
-------	--

14:00	IFCB is close Camera is adjusted horizontally → MOV_0152.MP4 Expert tab still on debubble x3
-------	---

14:10	Start Acq Inline Gain 0.6 0.60 First Alignment was checking view image
-------	---

Date	Time	Note
2015/11/8	13:29	Set PMT B to 0.65 instead of 0.60
		Size of waves increased → 7-8 beautiful
2015/11/10	1:36	Adjust focus +100
		→ Some set of images are centered vertically others are completely on top
	4:57	→ got a lot of bubble
	12:50	→ stop Acq start debubbling change configuration of intake
		Might be an issue with vertical distribution of IFCB due to wave motion of the boat
	13:12	Chlorox + Biocide + Debubble
	13:30	Start Acq Trigger on fluorescence 1 Syringe → Inline system stopping from here
		Bubble in might be due to cold water ↳ condensation happened in the ACS
	14:44	Restart acq
	15:57	Bubbles again in the IFCB start debubbling
	16:30	Start acq
	18:33	Stop acq - Start Debubble Water < 4°C
	18:51	Rotate IFCB 180° ↳ set intake closer, shorten intake tubing

Date	Time	Note
2015/11/10	20:11	Start acquisition
	21:50	Stop Acquisition → bubble on 3 rd syringe Debubble x2
		Volume to skip 0.5 ml
	22:00	activate Debubble with sample (last volume)
		Start Acquisition
2015/11/10	10:40	IFCB / humidity keep going up 13.3% temperature going down 27°C
2015/11/12	16:45	Stop Acq All the acquisition of 11m are run with Debubble with sample 16:45 Start Acq Stn 1 Bottle 8, 5m File: D2015 11 12 T 164441 - IFCB 107 → 1037 frames & targets
	17:10	Start Acq Stn 1 Bottle 7, 10m File: D2015 11 12 T 171051 - IFCB 107 → 1395 frames 1268 targets
	17:43	Start Acq Stn 1 Bottle 6, 25m File D2015 11 12 T 174340 - IFCB 107 → 1007 frames 905 targets
	18:10	Start Stn 1 Bottle 5, 50m File D2015 11 12 T 181014 - IFCB 107 → 929 frames 823 targets

Date	Time (UTC)	Note
2015/11/12	18:40	File: D2015-11-12T183934 - IFCB107 Start Acq Sta 1 Bottle 4 75m → 910 ^{frames} 815 targets
19:10		Start Acq Sta 1 Bottle 3 100m File D2015-11-12T190934 - IFCB107 → 0  Restart Acq with same Bottle File D2015-11-12T192127 - IFCB107 → 1047 frames 945 targets
19:47		Start Acq Sta 1 Bottle 2 150m File D2015-11-12T194732 - IFCB107 → 58 frames 55 targets
20:33		Start Acq Sta 1 Bottle 1 200m File D2015-11-12T203330 - IFCB107 → 90 frames 86 targets
21:19		Start Acq Inline with + Debubble with active Debubble with Sample

Date	Time (UTC)	Note
2015/11/14	18:39	Acq Stop • Station 2 Bottle 8 5m File: D2015-11-14T184138 - IFCB107 → 2527 frames 2222 targets
		• Station 2 Bottle 7 10m File: D2015-11-14T160843 - IFCB107 → 2381 frames 2082 targets
		• Station 2 Bottle 6 25m File: D2015-11-14T164016 - IFCB107 → 2350 frames 1996 targets
		• Station 2 Bottle 5 50m File: D2015-11-14T170539 - IFCB107 → 2718 frames 2320 targets
		• Station 2 Bottle 4 75m File D2015-11-14T174811 - IFCB107 → 1836 frames 1520 targets
		• Station 2 Bottle 3 100m File D2015-11-14T181437 - IFCB107 → 1906 frames 1528 targets
		• Sta 2 Bottle 2 150m File D2015-11-14T185017 - IFCB107 → 276 frames 239 targets
		• Sta 2 Bottle 1 200m File D2015-11-14T192649 - IFCB107 → ^{File Targets}

Date Time (UT) Note
 2015/11/15 10:00 IFCB intake and exhaust were unplugged
 Debubble x 3
 11:23 Close
 Biocide
 11:38.43 Debubble with Sampling → Start Acq
 12:23 Set Focus - 100
 13:06 Set Focus + 200
 16:45 Start debubbling
 Or some bubbles in every sample
 (1-3)
 Reactivate Debubble with sample

2015/11/16 6:55 Sample Position are still all over the place
 ↳ there is probably bubble in the shift fluid and filler
 → Run Sample 2 Cone

- Open IFCB
 refill filler with TEAN
 issue of contact with ethanol cable when closing

- Close IFCB
 still bubble
 ROTs randomly distributed
 lot out of focus

9:14 Switch to pump 2

Date Time Note
 14:57 No more bubbles but position of ROI is bad
 15:29 Stop Acq
 Start Acq with ^{pump 2} Debubble + Backflush
 Stn 3 ~~Botle 6~~ Botle 6 75 m
 File: D20151116T-153239-IFCB107
 130 Targets + 1 bubble
 155854 → 89 targets
 D20151116T 162232 - IFCB-107
 ↳ 103 Targets
 Botle 5 50 m
 D20151116T 170626 - IFCB107 ^{Targets} → 2031
 1731:55 → 872
 175924 → 875

Botle 8 5 m
 D20151116T 183115 - IFCB107 → 944
 1856.64 - IFCB107 → 708
 192213 → 834

- Run 4ml with Debubble x 15 Fast x 10 times
 ↳ no particles output
 at 30min/run

The micro track

- Prepare 2% Micro (1ml of Micro 90 and 50ml of DI)
 → turn off Pump (turn off sheet)
 → run sample fast x 15) shut off
 → run debubble
 → run sample, half way turn on pump → no big bubble going through
 → debubble (sheet on)
 → run 10 seconds to flush micro from system x 500 times
 ↳ 5ml, 15x fast

Date	Time (UTC)	Note
2015/11/16	22:08	Start Acq Pump 1 Debubble with Sample 5mL Output file Blob analysis PMT B → trigger fluorescence only Clean away 50 Run Fast double View images off debug off Active

23:12 Stop Acq → ROI distribution improved but not good enough
Run micro lock again
Start Acq again

2015/11/17 12:31 IFCB run correctly again
↳ position of ROI is way better after a night of sampling

2015/11/18 14:32 IFCB Stop Acq
→ Run 3 times Samples at 150, 100 and 10mm
Stn 4 1 time at all depth concentrated

20:17 Start IFCB Acq

Date	Time (UTC)	Note
2015/11/20	12:21	Stop Acq file 122019 → is empty run few seconds Bottle 7, 6, 5, 3 → 1 run non concentrated * → 1 run concentrated → backflush with sample

20:10 Start Acq as 120111
↳ uncheck backflush with sample

2015/11/21 15:50 take sample from inline to compare w/ filtered inline.
1 liter → 43ml

16:04 Stop Acq
~~16:06:27~~
16:17:39 Run concentrated sample
↳ ~~Backflush + Debubble~~
↳ ~~Backflush + Debubble~~
x3
→ adjust focus +200 on first run

18:14:28 Start Acq again

2015/11/22 17:35 Stop Acq
11:36:59 Start Acq + Backflush
→ Concentrated sample of BioLead 1 Stn 6

13:17:57 Start Acq Inline

2015/11/23 13:06 Stop Acq
→ T126903 is only one left way

13:08:55 Start Acq for sample + Backflush

22:1400 Start Acq Inline

15/11/24 13:32 Stop Acq
13:33:04 Start Acq Samples Sta 7 (day 2)
13:39:31 → close software by accident
Start Acq Samples Sta 7 backflush

20:45:00 Start Acq Inline
debubble on backflush off

15/11/25 12:19 Stop Acq
12:20:00 Start Acq Samples Sta 7 (day 2)
↳ Acquisition start by itself after the software stop 2x
in backflush

15/11/25 18:52:52 Start Acq Inline

15/11/26 00:59:24 Vertical Alignment issue

15/11/27 2:34 Acq Stop
→ might be due to drop in temperature of water
M/26 18:00 → 20°C
M/27 2:30 → 10°C
M/27 4:00 → 8°C
M/27 00:30 → 15°C
M/27 1:45 → 10°C
→ Close
→ Bypass
→ Beads → unable to see anything

3:10 Try Pump 2
Run Fast x 15
+ debubble + backflush - output

3:43 → Not better T032857

4:01 → Seems Good At 2nd syringe T05441
in Acq + Backflush + Debubble + beads very 50
→ may be a little too high

12:26 Acq Stop → Vert Align Issue

12:26:08 Start Acq Fast x 15 + debubble + backflush
No output

15/11/30 22:15 Stop Acq
End of cruise

22:18:20 Start Acq with Chlorox
run fast x 5