

SEA-BIRD ELECTRONICS, INC.

1808 136th Place N.E., Bellevue, Washington 98005 USA Telephone: (425) 643-9866 Telex: 292915 SBEI UR Fax: (425) 643-9954 email: seabird@seabird.com

1	DATE	SYM	REVISION RECORD	AUTH	DR	CHK

SBE P/N 50145

SBE 32-12/16Pl to SBE 9plus mount kit

KIT CONTENTS

SBE P/N	Manufacturer P/N	Primary SBE Application	QTY
23094	SBE 9plus cage insulator	Provide electrical insulation between cage and CTD endcaps	4
23844C	SBE 32 to 9plus CTD mount	Main cage assembly for mounting CTD to Carousel	1
30142	Machine screw, 6-32 x 3/8 PH	Securing screws for 9plus cage insulator	4
30194	Bolt, 3/8-16 x 1-1/4 Hex, SS	Securing bolts for CTD cage clamps	4
30258	Washer, 3/8 split ring lock	Used with CTD securing bolts (30194)	4
30409	Teflon Tape, Adhesive 1 side	Provides electrical insulation between CTD and cage clamps	3 feet

Refer to Assembly Drawing 67069 for details.

A. Remove Carousel hardware

- 1. Stand Carousel system upright, such that pylon latch assembly is to the top.
- 2. Hardware from 4 bolts (PN 30603, ¹/₂-13 x 3-1/2") will need to be removed.
- 3. Do not remove the bolts, as they will still hold upper portion of carousel frame assembly in place.
- 4. Hold all hardware in a try until cage is installed.

B. Install cage insulators.

- 1. Cage insulators install on outside of cage at the point where the clamps will intersect with the 9plus housing and endcaps.
- 2. Secure each clamp with 1 screw (30142).
- 3. Note on correctly installing insulators.
 - a. Screw hole on insulator is offset.
 - b. Insulator installs with short half facing CTD and long half facing side of cage.
 - c. A correctly installed insulator will be flushed against 3 sides of its bar, with no portions of the insulator hanging over the edge of the cage frame parts.


C. Install CTD Cage

- 1. CTD cage (23844C) part number includes cage and mount brackets.
- 2. Cage portion will install onto the 4 loosened bolts such that welded half of mounting brackets forms a trough.
- 3. Hold cage in place and re-fasten hardware onto the bolts.
- 4. Install flat washer first, followed by lock washer.
- 5. Secure with the same nut that you removed.

D. Install CTD

- 1. CTD lays into the trough made by the 2 mount brackets.
- 2. The 2 clamp portions are placed on top of CTD such that kit hardware will fit into cage clamps.
- 3. Secure clamps to cage with 1 lock washer (30258) first, and followed with 1 bolt (30194) well coated in Never-Seez lubricant.

<u>SBE DRAWING:</u> 67069	Sea-Bird Electronics Procedure
<u>TITLE:</u> SBE 32 12/16 to SBE 9plus Mount Kit Assembly	PROCEDURE NUMBER: 67069 TITLE: SBE PN 50145 Carousel to 9plus Mount Kit REVISION:
<u>REV:</u>	EFFECTIVE DATE: 11/20/2002 CHECKED BY: PAGE 1 of 1



DATE	SYM	REVISION RECORD	AUTH.	DR.	CK.

LOWER GUARD/BOTTOM ADAPTER PLATE ASSEMBLY (SIDE VIEW) (4 PLACES FOR MOUNT ATTACHMENT)

P/N 23844C, SBE32 12/16 9P CTD MOUNT

	Station of the Armenian P. Self.				
TOLERANCES	FOLERANCES SEA-BIRD ELECTRONICS, IN				INC
FRACTIONAL	P/N 50	145	SCALE NTS	DRAWN BY APPROVED BY	CEG RB
DECIMAL	ME SBE32 12/16 TO SBE 9plus MOUNT KIT ASSEMBLY				
ANGULAR	DATE 12.29.98	DRAWING NU	MBER	67069	REV