
ac-s Repair Summary

Date 7/11/2017 Customer University of Maine

RO # 33917

S/N # acs007 Technician cad/dw

Cal # 16

Incoming Status/Noted Problems with ac Meter

- None.
-

Standard Service

- Replaced pressure housing seals
- Checked all internal components for wear and damage
- Replaced 'a' & 'c' lamps
- Cleaned all optical components
- Focused and aligned optics
- Checked filter wheel motor registration
- Performed stability and noise tests
- Replaced desiccant, performed vacuum purge
- Performed shake and pressure tests
- Performed temperature, air, and water calibrations
- Updated meter's calibration information
- Compiled customer CD with calibration, device file, and air tracking file

Additional Repairs

- Replaced all three Pressue Windows
- Replaced C side RX Lens
- Replaced A side TX Filter
- Replaced A side Beam Splitter
-
-
-

Comments

- None.