



Sea-Bird GmbH
 Postfach 1167, 87401 Kempten, Germany
 Phone: +49 831 9 60994 701 Fax: +49 831 960994 709
 Email: seabird.eu@seabird.com

Service
Report

RMA Number	E11776
-------------------	--------

Customer Information:

Date	2/24/2021
-------------	-----------

Company	EMS/Spain
Contact	Josep M ^a Erta
PO Number	T1871

Serial Number	03P5146
Model Number	SBE 03

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.
3. Performed internal inspection and O-ring replacement.
4. Backfilled sensor with ARGON gas.
5. Performed "Final" calibration of the temperature sensor.
6. Backfilled sensor with ARGON gas.
7. Performed hydrostatic pressure test.
8. Performed "Final" calibration of the temperature sensor.
9. Performed "Final" calibration of the temperature sensor.

Special Notes:

--



Sea-Bird GmbH
Postfach 1167, 87401 Kempten, Germany
Phone: +49 831 9 60994 701 Fax: +49 831 960994 709
Email: seabird.eu@seabird.com

Service
Report

RMA Number	E11776
-------------------	--------

Customer Information:

Date	2/24/2021
-------------	-----------

Company	EMS/Spain
Contact	Josep M ^a Erta
PO Number	T1871

Serial Number	QCP2350-70491
Model Number	BIO

Services Requested:

1. Return to manufacturer for service and calibration.

Problems Found:

Services Performed:

1. Sent to Biospherical for calibration/repair.*

Special Notes: