PO Box 518 620 Applegate St. Philomath, OR 97370



(541) 929-5650 Fax (541) 929-5277 www.wetlabs.com

ac-s Repair Summary

Date 1/22/2015 Customer University of Maine RO # 025336

S/N # 091 Technician CAD/bw Cal # 6

Incoming Status/Noted Problems with ac Meter

- Motor is pulling excessive current. Hub bearing is noisy/dragging.
- No other problems noted.
- •
- .
- •
- •

Standard Service

- Replaced pressure housing seals
- Checked all internal components for wear and damage
- Replaced 'a' & 'c' lamps
- Cleaned all optical components
- Focused and aligned optics
- Checked filter wheel motor registration
- Performed stability and noise tests
- Replaced desiccant, performed vacuum purge
- Performed shake and pressure tests
- Performed temperature, air, and water calibrations
- Updated meter's calibration information
- Compiled customer CD with calibration, device file, and air tracking file

Additional Repairs

- Replaced motor and hub bearing.
- No other repairs required.
- _
- •
- •
- .

Comments

•