

## SEA-BIRD ELECTRONICS, INC.

1808 136th Place N.E., Bellevue, Washington 98005 USA Telephone: (425) 643-9866 Telex: 292915 SBEI UR

Fax: (425) 643-9954 email: seabird@seabird.com

## SBE P/N 50196

DATE	SYM	REVISION RECORD	AUTH	DR	CHK

# SBE 32 24-Place Datasonics Mount Kit

### KIT CONTENTS

SBE P/N	Manufacturer P/N	Primary SBE Application	QTY
231056	SBE 32 12/24Pl Datasonics Mount Plate	Main Sensor Securing Plate	1
231141	SBE 32 24Pl Datasonics Mount Bar	Secures Mount Plate to Carousel Stand	1
23859	SBE 32 Datasonics Mount Brackets	Secures Datasonics to Mount Plate	2

#### *HARDWARE*

SBE P/N	Part Description	Primary SBE Application	QTY
30210	Nut 3/8-16 Nylon Stop	Used with Mount Plate Securing Bolts	4
30254	Washer, 1/4" Split Ring Lock	Used with Datasonics Mount Brackets	4
30257	Washer, 3/8" Flat SS	Used with Mount Plate Securing Bolts	8
30377	Bolt, 1/4-20 x 1-1/4 Socket	Datasonics Mount Bracket Securing Screws	6
30570	Washer, 1/4" Flat SS	Used with Datasonics Mount Brackets	4
30840	Bolt, 3/8-16 x 3-1/2 Hex	Mount Plate Securing Screws	4

### A. Background

- 1. Refer to SBE Assembly Drawing, number 67087 for a detailed explanation of included parts, and further assembly instructions.
- 2. Do not overtighten screws into Celcon, as it may crack the Celcon material.

### **B.** Assembling the Fixture

- 1. Mount clamps (23859) to plate (231056) with screws and washers (30377, 30254, 30570).
- 2. Install screw (30377) loosely into open end of each clamp.
- 3. Slide Bolts (30840) and washers (30257) through plate. Fit plate and mount block (231141) together around vertical extension stand bar.
- 4. Secure Plate and block to bar with nut (30210) and washer (30257).

### C. Installing Datasonics Altimeter

- 1. Slide Altimeter through mount clamps (23859) such that sensor end faces down, and unit is vertically centered between the clamps.
- 2. Tighten 30377 bolts on open end of clamps just until they can hold the sensor's weight. Turn each screw up to ¼ turn farther to insure proper tension.
- 3. An overtightened screw will cause the clamp to crack. An undertightened screw will allow the sensor to fall out of the block.

SBE DRAWING: 67087

TITLE: SBE 32 24-Place Datasonics Extension Stand Mount Kit Assembly

REV:

## **Sea-Bird Electronics Procedure**

PROCEDURE NUMBER: 67087.1

**TITLE: SBE 32 24-Place Datasonics Mount Kit** 

**REVISION:** 

**EFFECTIVE DATE: 11/25/2002** 

CHECKED BY: \_\_\_\_\_ PAGE 1 of 1

