

SEA-BIRD ELECTRONICS, INC.

1808 136th Place N.E., Bellevue, Washington 98005 USA Telephone: (425) 643-9866 Telex: 292915 SBEI UR Fax: (425) 643-9954 email: seabird@seabird.com

SBE P/N 50075

DATE	SYM	REVISION RECORD	AUTH	DR	CHK
11.02	В	Restored Original Assembly Drawing	MJ	MJ	
9.1.04	С	Changed Clamp	CB	KLP	

Seacat to Li-Cor Par Sensor Mount Kit Assembly

Kit Contents

SBE P/N	Description	Primary SBE Application	QTY
231949	Seacat Li-Cor Mount Block #1	Main Sensor Mount Assembly	1
231950	Seacat Li-Cor Mount Block #2	Main Sensor Mount Assembly	1
30158	Mach screw, 8-32 x 3/4 PH SS	Secures Li-Cor sensor into Mount	2
30409	Teflon Tape	Installed on Hose Clamp 30379	
30988	Hose Clamp, AWAB 316 SS, #80	Secures Mount Clamp to Seacat Housing	1

Mount Block Assembly

Drawing number 50137

A. Installing the Li-Cor Sensor

- 1. Set sensor into mount (P/N 231949) as shown in SBE DWG 50137. Secure to mount half ring (P/N 231950) attachment and 30158 hardware.
- 2. Wrap hose clamp around Seacat and Mount, such that Teflon tape coated areas are in contact with Seacat housing.
- 3. If the Seacat Housing is metal, make sure that no Steel from the hose clamp is in contact with the housing.
- 4. Tighten hose clamp hand-tight.

SBE Drawings:

50137 Li-Cor Mount Procedure

PROCEDURE NUMBER: 67002
TITLE: Li-Cor Mount Procedure

REVISION: C

EFFECTIVE DATE: 9/1/2004

CHECKED BY:

