

Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 2186
CALIBRATION DATE: 21-Jan-16

SBE 4 CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -1.02666398e+001
h = 1.36742688e+000
i = -2.52121751e-003
j = 2.28055262e-004

CPcor = -9.5700e-008 (nominal)
CTcor = 3.2500e-006 (nominal)

BATH TEMP (° C)	BATH SAL (PSU)	BATH COND (S/m)	INSTRUMENT OUTPUT (kHz)	INSTRUMENT COND (S/m)	RESIDUAL (S/m)
0.0000	0.0000	0.00000	2.74530	0.00000	0.00000
-1.0000	34.5566	2.78560	5.29352	2.78558	-0.00002
1.0000	34.5566	2.95587	5.41051	2.95589	0.00002
15.0000	34.5564	4.24309	6.22363	4.24310	0.00001
18.5000	34.5558	4.58753	6.42365	4.58752	-0.00001
29.0000	34.5548	5.66429	7.01193	5.66427	-0.00002
32.5000	34.5494	6.03469	7.20310	6.03470	0.00002

f = Instrument Output (kHz)

t = temperature (°C); p = pressure (decibars); δ = CTcor; ϵ = CPcor;

Conductivity (S/m) = $(g + h * f^2 + i * f^3 + j * f^4) / 10 (1 + \delta * t + \epsilon * p)$

Residual (Siemens/meter) = instrument conductivity - bath conductivity

