



Sea-Bird Electronics, Inc.
13431 NE 20th Street
Bellevue, WA 98005
USA

Phone: (425) 643-9866
Fax: (425) 643-9954
E-mail: seabird@seabird.com
Web: www.seabird.com

FIELD SERVICE BULLETIN NO. 1

August 1997

PRODUCT RECALL NOTICE

Opto-Isolated Junction Boxes (with or without NMEA 0183 Interface)



A POTENTIALLY DANGEROUS CONDITION MAY EXIST IN SEVERAL VERSIONS OF OPTO-ISOLATED JUNCTION BOXES HAVING EXTERNAL FUSE HOLDERS.

(If you are not the user of this equipment, PLEASE communicate this information to the appropriate person or department.)

Equipment Affected

All versions of opto-isolated type junction boxes (similar to above) WITH EXTERNAL FUSE HOLDERS. If your opto box does not have an external fuse holder, DISREGARD THIS NOTICE.

Description

The panel mounted fuse holder on these units is likely to be wired with the "hot" wire connected to the front terminal (on the inside of the box). This condition presents a risk of electric shock if the fuse is removed from the fuse holder while the junction box is connected to an AC power source and you contact the fuse area.

***While it should be a commonly practiced safety measure, we reiterate:
NEVER WORK ON ELECTRONIC EQUIPMENT THAT IS PLUGGED INTO A POWER SOURCE.***

Immediate Action

Contact Sea-Bird to request a warning label to be applied.

And... always unplug junction box before changing the fuse!!!

As Soon as Practical

Send your junction box to Sea-Bird for modification to eliminate the shock hazard. Your junction box can be returned to Sea-Bird using our Federal Express account number. We will make the necessary modifications and return your box within a week of receipt. Contact our customer service department for account number and instructions on returning your junction box. Two-way transportation and repair costs will be covered by Sea-Bird Electronics, Inc.