



Sea-Bird Electronics, Inc.
 13431 NE 20th Street
 Bellevue, WA 98005 United States

Phone
 Fax

+1-425-643-9866
 +1-425-643-9954
 www.seabird.com

SERVICE REPORT

Service Request
Date
Sales Order

1005509707
 19-FEB-2020
 201435567

CUSTOMER INFORMATION

Name: FONDATION TARA OCEAN
 Account : 40328346
 LOU TISNE
 lou@fondationtaraocean.org
 33-078-3163268

PO Number:

Bill To Address

8 RUE DE PRAGUES
 PARIS, ILE DE FRANCE, 75012, FR

Ship To Address

IMEV- 181 CHEMIN DU LAZARET
 VILLEFRANCHE, ALPES MARITIME, 06230, FR

REQUESTED SERVICE DETAILS:
 INSTALL ANTIFOUL: No

REQUESTED TRANSACTION DETAILS:
 PAPER COPIES: Yes
 SPLIT SHIP: together

PRODUCT INFORMATION

Item: 43.LEGACY
Item Description: (LEGACY) SBE 43 Oxygen Sensor
Serial: 431638

Special Notes

Services Requested:
 Dissolved Oxygen Calibration
 O-Ring Replacement & Hydrostatic Test

Problems Found:

The membrane was found to have ballooned.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Unbilled Items

Item	Item Description	Qty
31087	PRESSURE COMPENSATION BAG, SBE43, DWG /21716A	1
801576	SBE43 LID & MEMBRANE SUB-ASSY, .5MIL MEMBRANE	1



Sea-Bird Electronics, Inc.
 13431 NE 20th Street
 Bellevue, WA 98005 United States

Phone
 Fax

+1-425-643-9866
 +1-425-643-9954
 www.seabird.com

SERVICE REPORT

Service Request
Date
Sales Order

1005509707
 19-FEB-2020
 201435567

PRODUCT INFORMATION

Item: 43.LEGACY
Item Description: (LEGACY) SBE 43 Oxygen Sensor
Serial: 431639

Special Notes

Services Requested:
 Dissolved Oxygen Calibration
 O-Ring Replacement & Hydrostatic Test

Problems Found:
 Air was found in the electrolyte.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Unbilled Items

Item	Item Description	Qty
801576	SBE43 LID & MEMBRANE SUB-ASSY, .5MIL MEMBRANE	1
801230	SBE43 ANODE SUB-ASSEMBLY / DWG 41092	1
801229	SBE43 GETTER SUB-ASSEMBLY / DWG 41091	1
22085	BATTERY, SANYO CR14250SE-SP1-1, 850 mA-h	2



Sea-Bird Electronics, Inc.
 13431 NE 20th Street
 Bellevue, WA 98005 United States

Phone
 Fax

+1-425-643-9866
 +1-425-643-9954
 www.seabird.com

SERVICE REPORT

Service Request
Date
Sales Order

1005509707
 19-FEB-2020
 201435567

PRODUCT INFORMATION

Item: 43.LEGACY
Item Description: (LEGACY) SBE 43 Oxygen Sensor
Serial: 432132

Special Notes

Services Requested:
 Dissolved Oxygen Calibration
 O-Ring Replacement & Hydrostatic Test

Services Performed:
 Perform initial diagnostic evaluation.
 Performed "POST" cruise calibration.
 Replaced the O-rings.
 Performed a hydrostatic pressure test.
 Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Unbilled Items

Item	Item Description	Qty