

PO Box 518
620 Applegate St.
Philomath, OR 97370



(541) 929-5650
Fax (541) 929-5277
www.wetlabs.com

ac-s Repair Summary

Date 12/5/2016 Customer University of Maine

RO # 32274

S/N # acs279 Technician cad/bw

Cal # 2

Incoming Status/Noted Problems with ac Meter

- No service or repair actions taken.
-
-
-
-
-
-

Standard Service

- Replaced pressure housing seals
- Checked all internal components for wear and damage
- Replaced 'a' & 'c' lamps
- Cleaned all optical components
- Focused and aligned optics
- Checked filter wheel motor registration
- Performed stability and noise tests
- Replaced desiccant, performed vacuum purge
- Performed shake and pressure tests
- Performed temperature, air, and water calibrations
- Updated meter's calibration information
- Compiled customer CD with calibration, device file, and air tracking file

Additional Repairs

- Performed temp cal to 45C only. Air and water cals are not affected.
-
-
-
-
-
-

Comments

-